## **Precision Machining Technology**

## **Program Outcomes**

1 Togram Gatcomes						
Program, set-up and	Program, set-up and	Program, set-up and	Program, set-up and	Program, set-up and	Prepare cutting tool	Inspect, adjust and
operate live tooling	operate dual spindle	operate 3-D surfacing	operate 4 axis	operate 5 axis	calculations from	complete a machine-
equipment	equipment	equipment	equipment	equipment	manufacturer's book	job package
					recommendations	
1	[	1				
R,A	R,A					
		R,A				
			I	I		
			R,A	R,A	I,A	I,A
	Program, set-up and operate live tooling equipment	Program, set-up and operate live tooling equipment Program, set-up and operate dual spindle equipment	Program, set-up and operate live tooling equipment  Program, set-up and operate dual spindle equipment  Program, set-up and operate 3-D surfacing equipment  I I I I I I R,A R,A R,A	Program, set-up and operate live tooling equipment Program, set-up and operate live tooling equipment Program, set-up and operate 3-D surfacing equipment equipment equipment Program, set-up and operate 4 axis equipment  I I I I I I I I I I I I I I I I I I I	Program, set-up and operate live tooling equipment Program, set-up and operate live tooling equipment Program, set-up and operate dual spindle equipment Program, set-up and operate 4 axis equipment Program, set-up and operate 4 axis equipment Program, set-up and operate 5 axis equipment Pro	Program, set-up and operate dual spindle equipment  Program, set-up and operate dual spindle equipment  Program, set-up and operate dual spindle equipment  Program, set-up and operate 4 axis equipment  Program, set-up and operate 5-D surfacing equipment  Program, set-up and operate 5 axis  Program, set-up a

I-Outcome introduced; R-Outcome Reinforced; E-Outcome Emphasized; A-Outcome Assessed